

SITE FACT SHEET

200-Line Dump *Site 1*



Description: The 200-Line Dump is an inactive, covered, and heavily vegetated dump site situated to the east of Neah Bay on 200-Line Road. Metal debris, including vehicles, drums, and kitchen appliances, is present in the dump. An old roadbed borders the dump to the west. The site slopes downward to the west toward Agency Creek and to the south toward a small, intermittent creek that flows into Agency Creek.

Community Impacts: Potential impacts to subsurface soil, ground water, and the nearby creeks.

Investigations and Actions to Date: Site inspections were performed by the Makah Environmental Restoration Team in October 2000 and in March and April 2004. The site was investigated along with 9 other sites during the 2004 limited remedial investigation, when soil samples were collected. Sediment and surface water samples were collected during the March 2006 annual monitoring.

Planned Activities: Collect surface water and sediment samples from the nearby streams on a semi-annual basis; develop feasibility study to assess waste removal.