

# SITE FACT SHEET

## Top Camp Dam *Site 20*



**Description:** The Top Camp Dam site is an abandoned water system consisting of a small concrete dam, a water treatment building/pumphouse, an impoundment, and a pipe system. The age of the facility is unknown. It was constructed to replace the water-supply pipeline system from the Cantonment Area to Top Camp and was used until the Makah AFS was closed in 1988. The water system supplied the Top Camp area.

**Community Impacts:** Abandoned structures; the dam impacts the natural hydrology.

**Investigations and Actions to Date:** Site inspections were performed by the Makah Environmental Restoration Team in October 2000 and in March and April 2004. The site was investigated along with 9 other sites during the 2004 limited remedial investigation; soil, asbestos, and lead-based paint samples were collected (no contaminants were detected at concentrations above screening levels).

**Planned Activities:** Work with Makah Fisheries to plan dam removal; deconstruct and remove abandoned structures; remove the dam.